3/4"-2" Gas-Free Safe-T-Stopper Skinner Tee Kit

Stop off Skinner tees and plug the main through a ball valve, with everything the crew needs in one case.





Stop-off uses a self tap plug.

Skinner Tool and Jaws remove valve screw gas-free.

ORDER

KIT#: 54-75020SKINR

SKINNER SAFE-T-STOPPER KIT

Contact your local sales rep or distributor

HOW IT WORKS

1. Mount the Thread Adapter and Ball Valve on the tee.
2. Remove the Skinner Screw from the tee with the Skinner Tool and jaws.
3. Install the Self Tap Plug through the valve with the Stopping Tool. Bleed off and confirm a full stop at the meter.
4. Remove the valve and adapter, then abandon the tee per company procedures.



PLCS

(856) 722-1333 info@plcsusa.com www.plcsusa.com